

# **Christ Our Savior Catholic School**

## **Asbestos Content and Management Plan**

September 1, 2009

In 1986, Congress passed the Asbestos Hazard Emergency Response Act (AHERA). The law requires all schools, kindergarten through twelfth grade, to be inspected and to identify any asbestos-containing building materials. The law further requires the development of a Management Plan, based upon the findings of the inspection, which outlines our intent in controlling the potential for exposure to asbestos fibers in our school.

In the past, asbestos was used extensively in building materials because of its insulation and fire retarding capabilities. Virtually any building built before the 1970's contains at least some asbestos in pipe insulation and structural fireproofing. We too have buildings that contain asbestos material. The primary concerns arise when these materials begin to deteriorate or become damaged.

Christ Our Savior Catholic School has been inspected and some asbestos containing materials were identified in the building. The materials are distributed in various locations and include floor tile, pipe insulation and mechanical areas not readily accessible to building occupants or students.

The school's Inspection Report and Management Plan outlines in detail the methods used to maintain the materials in a safe manner. In addition, as required by law, appropriate school staff members have been trained to administer this program.

A copy of the inspection report and the management plan is on file in the school office for review if you so desire.

Sincerely,  
Ms. Cynthia Rogers  
Campus Principal